



U.S. Department  
of Transportation  
Federal Motor Carrier  
Safety Administration

1200 New Jersey Avenue, SE  
Washington, DC 20590

Grupo Behr de Baja California SA de CV  
Boulevard Bellas Artes # 17686-116  
Tijuana, Baja California Norte 22509  
MEXICO

SERVICE DATE: AUG 30 2013

In Reply Refer to: MC-ESB  
MX Number: 630115  
USDOT Number: 861744X

Mailing Address:

Grupo Behr de Baja California SA de CV  
2498 Roll Drive  
PMB 506  
San Diego, CA 92154

The motor carrier safety rating for Grupo Behr de Baja California SA de CV is:

**SATISFACTORY**


This SATISFACTORY rating is the result of a compliance review and evaluation of the safety fitness of this carrier completed on July 30, 2013. A SATISFACTORY rating indicates that the company has adequate safety management controls in place at this time to ensure compliance with the safety fitness standard prescribed in 49 CFR § 385.5.

On February 19, 2013, Grupo Behr de Baja California SA de CV was granted a certificate of registration for Provisional Operating Authority (Provisional Operating Authority) to participate in the Cross-Border Long-Haul Pilot Program (Pilot Program) authorizing transportation in the United States beyond U.S. municipalities and commercial zones on the U.S.-Mexico border. Operations under the Provisional Operating Authority are subject to subpart B of Part 385 of Title 49 of the Code of Federal Regulations (49 CFR §§ 385.101 - 385.119) and the terms and conditions of the Pilot Program. You are reminded that while Grupo Behr de Baja California SA de CV remains in the safety monitoring program operating under Provisional Operating Authority, the Federal Motor Carrier Safety Administration (FMCSA) will continue to monitor your operating procedures to ensure compliance with all applicable U.S. safety regulations and the specific requirements of the Pilot Program.

Additionally, should you commit one or more of the violations described in 49 CFR § 385.105, you may be subject to an additional compliance review or required to submit a written response demonstrating corrective action. Failure to respond within 30 days to an Agency demand for a written response demonstrating corrective action will result in a suspension of your Provisional Operating Authority for the Pilot Program and may also affect your ability to operate under any OP-2 authority in the commercial zone.

If you have any questions or require further information, please contact your servicing FMCSA office in Otay Mesa at 2297 Niels Bohr Court, Suite 504, San Diego, CA 92154. The telephone number is (619) 710-8400.

Sincerely,



Joseph P. DeLorenzo  
Director, Office of Enforcement and  
Compliance

cc: Penru Royston, Process Agent  
Evilsizor Transportation Services LLC  
6657 W. Ottawa Ave. 03  
Littleton, CO 80128