			UNITE	D STATES	DEPARTME	NT OF TRAN	ISPORTAT	ΓΙΟΝ			
	US DO <sup>.</sup>	T# Leg	al: GRUPC	D BEHR DE	BAJA CALIF	ORNIA SA D	ECV				
	861744	· · · ·	erating (DB								
MC/MX #:	630115	RFC	#: GBB971	008165	Federal Ta	x ID:					
Review T	ype: Cor	npliance Re	eview (CR)								
Scope:	Prin	cipal Office	e	Location	of Review/A	udit: Compar	ny facility ir	n another coun	try <b>Territ</b> o	ory: E	
Operation	Types	Interstate	Intrastate	•							
(	Carrier:	Non-HM	N/A	Business:	Corporation						
S	hipper:	N/A	N/A	Gross Rev	/enue: \$593	,024.00	for y	ear ending: 1	12/31/2012		
Cargo	o Tank:	N/A	١				-	_			
Company	Physica	I Address									
BLVD BE	LLAS AF	RTES #176	86-116								
TIJUANA	, BN 225	09 MEXI	00								
Contact I	Name:	ROBE	RTO GARC		N QUIROS	en ny Grand Lindol de Mandel de Lindol de		her her for each of the first o			
Phone nu	umbers:	(1) 664-6	47-5501	( <b>2)</b> 619-8	343-2751	Fax					
E-Mail Ad	dress:	roberto	ogarcia@gr	upologix.cor	n						
Company	Mailing	Address:	an a								
2498 ROI		MB 506									
SAN DIE	GO, CA 🤅	92154									
Carrier Cl	assificat	ion									
Autho	rized for	Hire				, 1 100 T 1					
Cargo Cla	ssificati	on									
Gener	al Freigh	nt			****	*****		****			
Does car	rrier tran	sport plac	ardable qu	antities of l	HM? No						
Is an HM	Permit	required?			N/A						
Driver Inf	ormatio	n		3938년 (P							
		Inter	Intra	Average	trip leased	drivers/mont	t <b>h:</b> 0				
< 1	00 Miles	:	3			Total Driver	r <b>s:</b> 6				
>= 1	00 Miles	: 3				CDL Driver	<b>rs:</b> 6				
Equipmer	it 👘										
		Ov	vned Terr	n Leased T	rip Leased				rm Leased <sup>-</sup>	Frip Leas	ed
Truck			5	0	0	Truck Tra	actor	3	0		0
Traile	r		3	0	0	# 2 6 5					
Power units											
Percentage	e of time	used in the	U.S.:90								

MQ4GKWUS0R7AA



### GRUPO BEHR DE BAJA CALIFORNIA SA DE CV U.S. DOT #: 861744X

RFC #: GBB971008165

# Part A

Questions about this report or the Federal Motor Carrier Safety or Hazardous Materials regulations may be addressed to the Federal Motor Carrier Safety Administration at:

2297 Niels Bohr Court, Suite 204 San Diego (Otay Mesa), CA 92154 Phone: (619)710-8400 Fax:(619)710-2804

#### This report will be used to assess your safety compliance.

#### Person(s) Interviewed

Name: ROBERTO GARCIA DE LEON QUIROS Name:

Title: VICE PRESIDENT Title:





## 07/30/2013

1 FEDERAL	Primary: 382.401(c)(6)	Discovered 2	Checked 2	Drivers/Vehicles In Violation Checked 0 0
Description Failing to main Example DRIVER: TRIP DATE: 1 JANUARY TO JULY TO DEC	JUNE 2012.	alysis required b	y 40.29(g)(6).	
2 FEDERAL	Primary: 391.21(a)	Discovered	Checked 5	Drivers/Vehicles In Violation Checked 5 5
Description Using a driver Example DRIVER: TRIP DATE: 07	who has not completed and furnished an employment ap	plication.		
3 FEDERAL	Primary: 395.8(a)	Discovered	Checked 150	Drivers/Vehicles In Violation Checked 4 5
Description Failing to requi Example DRIVER: TRIP DATE: 04	re driver to make a record of duty status.			
4 FEDERAL	Primary: 395.8(f)	Discovered	Checked 5	Drivers/Vehicles In Violation Checked 1 2
Description Failing to requi Example DRIVER: TRIP DATE: 04 MISSING TOT		ner prescribed.	**********	
5 FEDERAL	Primary: 396.3(b)(2)	Discovered	Checked 5	Drivers/Vehicles In Violation Checked 5 5
Description Failing to have performed. Example DRIVER TRIP DATE: 05 VEHICLE: CA-		ious inspection	and maintenar	nce operations to be





## 07/30/2013

## **Part B Violations**

6 FEDERAL	Primary: 396.9(d)(3)			Discovered 36	Checked 68	In Vi	rivers/Vo olation 0	ehicles Checked 0
business. Example DRIVER: TRIP DATE: 07 VEHICLE: CA-9	//27/2012.	on form for 12 months f	rom the da	te of inspection	at the carrier's	s princ	ipal place	e of
Safety Fitness Rating Information:Total Miles Operated42,000Recordable Accidents1Recordable Accidents/Million Miles23.81			OOS Vehicle (CR): 0 Number of Vehicle Inspected (CR): 0 OOS Vehicle (MCMIS): 1 Number of Vehicles Inspected (MCMIS): 5					2
Your proposed s	afety rating is ·		Rating	Factors	A	cute	Critical	6078 - Hatoon - 1777 - <u>6</u> 7
rour proposed a	arety rating is .			tor 1:	S	0	0	
			Fac	tor 2:	S	0	0	
SATISFACTORY			Fac	tor 3:	S	0	0	
			Fac	tor 4:	S	0	0	
			Fac	tor 5:	N	0	0	
			Fac	tor 6:	S	-	-	

Corrective actions must be taken for any violations (deficiencies) identified on Part B of this report.





RFC #: GBB971008165

# Part B Requirements and/or Recommendations

- 1. If you have any questions concerning this report, please contact the Federal Motor Carrier Safety Administration, at Niels Bohr Ct., Suite 204, San Diego, CA 92154 and contact Jose Tello at 619-710-8435.
- 2. This review will result in a Safety Rating.
- 3. Conduct periodic internal reviews of your driver qualification, hours of service control, maintenance, accident analysis/reporting, training, and other safety systems to ensure continued compliance with the FMCSR.
- 4. For questions about DOT numbers or biennial updates: 800-832-5660 or 703-280-4001 For questions about licensing, authority or MC numbers: 202-366-9805 For questions about insurance: 202-385-2423 For household goods complaints: 888-DOT-SAFT (888-368-7238)
- 5. The Division Administrator will continue to consider preventability when a motor carrier contests a proposed safety fitness rating. The motor carrier may deem that the recordable accident rate is not a fair means of evaluating its accident factor 6 on the Compliance Review. If so the motor carrier must submit the

compelling evidence within five calendar days to:

Amy Hope

1325 J Street Suite 1540

Sacramento, CA. 95814

Compelling evidence should include (but is not limited to) official police accident reports and official insurance accident investigation reports.

- 6. Notice: Recurring violations of the same or related acute or critical regulations (violations of the same Part in Title 49, Code of Federal Regulations) that result in three enforcement actions within a six year period will cause the maximum penalties allowed by law to be assessed for the third enforcement action.
- 7. All motor carriers and truck drivers are needed to fight against terrorism and hijacking. You could be a target. Protect yourself, your trucks, your cargo, and your facilities.

Discuss with your employees/drivers the "Security Measures for Truck Drivers and Companies" which were provided and reviewed with motor carrier official.

- Return the completed roadside inspection form to the issuing agency at the address indicated on the form and retain a copy at the motor carrier's principal place of business or where the vehicle is housed for 12 months from the date of the inspection.
- **9.** Ensure you have a means of indicating the nature and due date of the various inspection and maintenance operations to be performed.

10. Notice: On October 1, 2005, the FMCSA published a final rule revising the hours of service regulations for



GRUPO BEHR DE BAJA CALIFORNIA SA DE CV



U.S. DOT #: 861744X

# Part B Requirements and/or Recommendations

commercial motor vehicle drivers. Under the new rule, driver may drive 11 hours after 10 consecutive hours off-duty, but may not drive beyond the 14th hour after coming on-duty. Similar to existing rules, drivers may not drive after being on-duty for 60 hours in a seven-consecutive-day period or 70 hours in an eight-consecutive-day-period. This on-duty cycle may be restarted whenever a driver takes at least 34 consecutive hours off-duty. A short haul provision was also added allowing drivers of property carrying CMV's which do not require a Commercial Driver's License for operation and who operate within a 150 air mile radius of their normal work reporting location are not required to keep records of duty status (RODS).

Carriers and commercial motor vehicle drivers are required to comply with the current hours-of-service rules through September 30, 2005. Compliance with the "new" regulations is mandatory for carriers, except passenger-carrying operations, beginning on October 1, 2005. Passenger-carrying motor carriers and drivers are not subject to the new maximum driving limits. For more information on these regulations, please access the FMCSA website at http://www.fmcsa.dot.gov/.

- 11. Require drivers to prepare records of duty status in the form and manner prescribed under part 395.8(f).
- **12.** If you want some drivers to use the 100 air-mile radius exemption, make sure that the drivers meet all terms of the exemption, including being released from duty no more than 12 hours from when they report for duty. Logs must be prepared if a driver does not meet the 12 hour requirement.
- 13. Laboratory must transmit aggregate statistical summary on semi-annual basis
- 14. Understand Why Compliance Saves Time and Money: Compliance with FMCSRs will not only save lives, but also saves your business time and money. Tracking how much your business spends on non-compliance activities can help you understand the many benefits of compliance to your business and why safety is good business.

• Document and Follow Through on Action Plans: Document and follow through on action plans to ensure the actions you are taking are creating improvement in safety management and compliance.

• NOTICE: A pattern and/or repeated violations of the same or related acute or critical regulations (violations of the same Part in Title 49, Code of Federal Regulations) will cause the maximum penalties allowed by law to be assessed under Section 222 of the Motor Carrier Safety Improvement Act of 1999 (MCSIA). A pattern of violations means two or more violations of acute and/or critical regulations in three or more Parts of Title 49, Code of Federal Regulations. Repeated violations means violation(s) of an acute regulation of the same Part of Title 49, Code of Federal Regulations discovered during any eligible investigation. Repeated violations means violation(s) of an acute regulation of the same Part of Title 49, Code of Federal Regulations discovered in an investigation after one or more closed enforcement actions within a six year period and/or violation(s) of a critical regulation in the same Part of Title 49, Code of Federal Regulations after two or more closed enforcement actions within a six year period.

• NOTICE: 49 CFR Part 391.23 requires prospective employers to, at a minimum, investigate a driver's employment information, crash record, and alcohol and controlled substances history from all employers the driver worked for within the previous 3 years.

The Pre-Employment Screening Program (PSP) is a screening tool that assists motor carriers in investigating crash history and roadside safety performance of prospective drivers. The PSP allows motor carriers to purchase 5 years of crash data and 3 years of roadside inspection data from the Federal Motor Carrier Safety Administration's (FMCSA) Motor Carrier Management Information System (MCMIS). Records are available 24 hours a day via Web request. Motor carriers should visit the following website for more information: http://www.psp.fmcsa.dot.gov/Pages/default.aspx

• All motor carriers and truck drivers are needed to fight against terrorism and hijacking. You could be a target. Protect yourself, your trucks, your cargo, and your facilities. Discuss with your employees/drivers the "Security"



GRUPO BEHR DE BAJA CALIFORNIA SA DE CV U.S. DOT #: 861744X

RFC #: GBB971008165

# Part B Requirements and/or Recommendations

Measures for Truck Drivers and Companies" which were provided and reviewed with motor carrier official. Motor carriers should visit the following website for more information: http://www.fmcsa.dot.gov/documents/Hijacking-Brochure.pdf

**15.** Ensure that all drivers are fully and properly qualified before operating in interstate commerce. Maintain a complete file as required for each driver, documenting the qualification process.



RFC #: GBB971008165

Review Date:

07/30/2013

# Safety Fitness Rating Explanation

This report lists the facts which were used to determine the Safety Fitness Rating for the above motor carrier. Federal and State violations are combined for rating purposes. However, only the federal or federal equivalent section number is shown below. A check mark identifies the range within which the data fell when determining the Safety Fitness Rating. All information within a FACTOR block relates only to that FACTOR.

FACTOR 1 VIOLATIONS AFFECTII NONE		<ul> <li>√ 0 Point = Satisfactory</li> <li>1 Point = Conditional</li> <li>&gt;1 Point = Unsatisfactory</li> </ul>
	TOTAL POINTS: 0 = SATISF	ACTORY
FACTOR 2 VIOLATIONS AFFECTIONS NONE	Driver Qualification (CFR Parts 382, 5 NG RATING POINTS TOTAL POINTS: 0 = SATISF	1 Point = Conditional >1 Point = Unsatisfactory
FACTOR 3 VIOLATIONS AFFECTIN NONE	Operational/Driving (CFR Parts 39 IG RATING POINTS TOTAL POINTS: 0 = SATISF	1 Point = Conditional >1 Point = Unsatisfactory
FACTOR 4 VIOLATIONS AFFECTIN NONE		rformance Data (OOS%)) of-Service (OOS) Percentage: 20.0 OOS = SATISFACTORY (see chart)
Fewer than 3 Inspections	3 or more	Inspections
Rate same as other Regulatory Factors 1, 2, and 3	OOS Less than 34% √ Satisfactory	OOS 34% or Higher Conditional
0 Point = Satisfactory 1 Point = Conditional >1 Point = Unsatisfactory	Conditional If a pattern of Non-Compliance with a Critical or an Acute Violation	Unsatisfactory If a pattern of Non-Compliance with a Critical or an Acute Violation
	azardous Material (CFR Parts 397, 171, 172, carrier of Hazardous Material	173, 177, 180)
FACTOR 6	Accident (Recordable Accident Rat	e)
	Recordable Accidents) X (1 million)) ÷ (Totangent Content of the tess Than Satisfactory because	
OVERALL SAFETY FITN Number of Factors (1-( Unsatisfactory 0	6) shown above as less than satisfactory Conditional	ATISFACTORY





U.S. DOT #: 861744X

# Review Date:

07/30/2013

	Number	of Factors		
ι	Unsatisfactory	Conditional	OVERALL RATING	
$\checkmark$	0	2 or fewer	Satisfactory	
	0	3 or more	Conditional	
	1	2 or fewer	Conditional	
	1	3 or more	Unsatisfactory	
	2	0 or more	Unsatisfactory	

